drobo

Drobo B810i Firmware
Release Notes
Release Date: Oct, 2021

CONTENTS

VERSION INFORMATION
KEY HIGHLIGHTS
KNOWN ISSUES
RELATED TECHNICAL DOCUMENTATION

VERSION INFORMATION

Drobo Firmware: Version 2.0.1 [10.43.116331]

KEY HIGHLIGHTS

This is a firmware update for B810i.

Key features in 2.0.1
- Add ability to view important events on the Drobo using Drobo Dashboard

Fixes in 2.0.1
- Improvements in unsafe power loss handling
- Fix for issue with 16TB and larger drives
- Fix for issue with HDDs being reported as SSDs
- Prevent archive disk drives being added to a diskpack
- Improve time to add very large SSDs to a diskpack
- Various stability improvements

Fixes in 2.0.0
- Improve stability
- Address issue with timeout on connections in certain configurations

Fixes in 1.3.5
- Bug fixes and performance related issues
- Support for 8TB drives and Samsung SSD 840 EVO

Fixes in 1.3.3
- Bug fix related to upgrade of packs from B800i

Enhancements & Fixes in 1.3.2
- Hyper-V support
- ESXi 6.0 support
- Support migration of diskpack from B800i->B810i
- Stability and performance improvements

Key Features in 1.3.1
- 64 TiB LUN support
- Supports 4KN drives
- Supports Physical tiering and hot data cache using front slot SSDs

KNOWN ISSUES

- None

BEST PRACTICES

In accordance with industry best practices, you should always backup your data before any firmware

upgrade. For more information, please visit www.drobo.com/support.

Make sure that you keep all software up to date. This includes Drobo Dashboard, which as of this writing the latest releases are 3.5.0 (Windows) and 3.6.1 (Mac).

RELATED TECHNICAL DOCUMENTATION

Current Drobo technical reference materials are available on the Drobo Support Website (http://www.drobo.com/support.html).This includes:

- *Knowledge Base*
- *Best Practices*
- *Product Documentation*